




**Orbital Sciences Corporation  
Launch Systems Group**

---

<b>QUALITY PROVISIONS STANDARD TEXT CODES</b>	
<b>TITLE</b>	<b>NUMBER 0732.3</b>
<b>CLOSE OUT PHOTOGRAPHS REQUIRED – ITEMS THAT INCLUDE PRINTED WIRING ASSEMBLIES</b>	<b>DATE</b> 1/14/09
<p>Included with the Product Acceptance Data Package shall be close out photographs of each item being delivered. The close out photographs shall be a series of photographs which document areas internal to the item that cannot be inspected without disassembly of the item. On Printed Wiring Assemblies (PWAs), the photographs shall show the top and bottom surfaces of each PWA prior to conformal coat and/or assembly into the housing, and the routing and securing of all internal wire harnesses prior to close out. The Supplier shall ensure that the photographs are of sufficient quality and clarity to allow Orbital to verify that final assembly of the item is consistent with the item's design and manufacturing requirements. Each photograph shall be identified with the part number and serial number of the item being photographed.</p>	
Supplier Quality Assurance: 	Date: 1-19-09
Mission Assurance: 	Date: 1-20-09
Supply Chain Reviewer: 	Date: 1/20/09