




**Orbital Sciences Corporation
Launch Systems Group**

QUALITY PROVISIONS STANDARD TEXT CODES	
TITLE	NUMBER 0812.2
ORBITAL INSPECTION OF BARE PRINTED WIRING BOARD REQUIRED PRIOR TO SUBSEQUENT OPERATIONS	DATE 1/14/09
<p>Inspection of the bare Printed Wiring Board(s) (PWB) must be accomplished by an Orbital Quality Assurance Representative prior to subsequent operations. Subsequent operations are defined as any actions performed in the placement of any electrical/mechanical components on the bare PWB. Prior to presentation of the PWBs for this inspection, the PWBs shall have completed all applicable manufacturing, testing and inspection, been accepted by the supplier, and meet all of the requirements of the purchase documents as directed and amended therein up to the point of subsequent operations being started. The supplier shall provide reasonable facilities, equipment, and assistance, including access to all quality records and related data for the PWBs. Compliance to this requirement shall be denoted by a stamp and/or signature of the authorized Orbital Quality Assurance representative on Orbital's PWB Source Inspection Record Form or the acceptance certificate/document of the designated organization with either to be included in the shipping documents package of the final item. Orbital desires at least 3 business days advance notice prior to the expected time of the presentation of the PWBs to Orbital for inspection. Relief from this inspection requirement may only be obtained via a written waiver of inspection requirement by Orbital Quality Assurance.</p>	
Supplier Quality Assurance: 	Date: 1-19-09
Mission Assurance: 	Date: 1-20-09
Supply Chain Reviewer: 	Date: 1/20/09