




**Orbital Sciences Corporation  
Launch Systems Group**

---

<b>QUALITY PROVISIONS STANDARD TEXT CODES</b>	
<b>TITLE</b>	<b>NUMBER 0811.5</b>
<b>ORBITAL INSPECTION OF COMPLETED ITEM AT SOURCE (SOURCE INSPECTION) REQUIRED</b>	<b>DATE</b> 1/22/09
<p>Inspection of the item(s) on this order shall be accomplished on-site by an authorized representative of Orbital Quality Assurance. Prior to presentation of the order for Orbital Source Inspection, the item(s) shall have completed all applicable manufacturing, testing, and inspection requirements and meet all requirements of the purchase documents as directed and amended therein. The supplier shall provide reasonable facilities, equipment, and assistance, including access to all quality records and related data for contracted goods. Compliance to this requirement shall be denoted by a stamp or signature of the authorized Orbital quality representative on the supplier's final certification document and/or an Orbital Source Inspection document. The document(s) stamped/signed must be included in the shipping documents package. Orbital requires at least ten business days notice prior to the expected time of the presentation of the item(s) to Orbital for final source inspection. Relief from this source inspection requirement may only be obtained with a written waiver of source inspection requirement from Orbital's Procurement Agent signed by Orbital's Supplier Quality Assurance representative.</p>	
Supplier Quality Assurance:  102901	Date: 1-22-09
Mission Assurance:  103296	Date: 1/22/09
Supply Chain Reviewer:  103527	Date: 1/22/09